


Crosstown continues to be open to suggestions as how they may improve their



Î

Audit






(date and comments)

Comments:



safety progrom.



SMAR Safety Chart Checked items in compliance Checked items in non-compliance Items that are not applicable Number of non-compliance resolved during this Safety Audit Number of non-compliance pending Total Items Evaluated



SMAR Performance Score Safety Level Performance Score

Audit Sc 97.9 % (Max Score 100%)

Safety Audit: Location/Contractor:

4/7

Revision (3) Date of Revision: August 20, 2010

Points Eval 140 Points Ach

EARG CAPITAL AND OPERATION SAFETY SERVICES













Safety Audit: Location/Contractor







5/7

EARG CAPITAL AND OPERATION SAFETY SERVICES

Site Observations

BChydro @

Crosstown currently has a workforce of six including the superintendant and safety officer. They are installing the vertical sections of the 48: dia. HVAC ducting on the left wall of Unit 6.

No	Connects	Remedial Action Taken
GUD	Made recommendations on improvements to the contractor's rescue plan for work on the Unit 6	Information only.
	Creations were not following their resone procedures for work on the Unit 6 scaffolding by not having the tripod brought down to one to one level above the work arra.	The contractor is to ensure correlations with their suffry procedures.
100	Crosstows has yet to conduct a practice-drill for the rescue plan for work on the unit 6 scuffold.	The contractor is to create compliance with WSDC 4.19(3) Energency Procedure (3) de lant more each pow emergency drift must be hald to consor environment and offentiveness of emergency are inserts and procedure, and a record of the drift insert be last. Crosstown has schoduled a resone psectice for Monday, March 21st.
F10	Crosstown is relying on Rosalas Safety to provide level 3 first sid coverage while their first aid is off site don to lack of Indging.	Information only.
ON	Reminded the contractor that he hazard assourcest for work within the sir duct will need to be done by a qualified person. This is information only as (Coustown has red contenenced work within the sir duct.	Constitution (in its courses compliance with VSIC 5.11. (i) It is because the control of the co
FIG	Two first aids since previous audit. One for pulled muscle in the shoulder and the other for a small cut to the arm.	Information only,
OS.	The contractor's notice of project is posted.	This was noted
- 1	Contractor RepcOSB 7	Mark Reynor David Whole Greg Quinlan
1	Contraction Manager The Construction Officer Totion/Area Manager The OSH Specialist The OSH Specialist	Mas Wing Joy Queller Joy Quell